



DFS client device channel plan and software operational declaration

Date: 2020-08-31

We, MICROSOFT CORPORATION, declare that the device, FCC ID: C3K1942 Model Name: 1942, does not have Ad Hoc on “non-US frequencies” and/or on “DFS frequencies”. Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device

CH	1	2	3	4	5	6	7	8	9	10	11
Frequency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Scan Type	Active	Active	Active	Active	Active	Active	Active	Active	Active	Active	Active
CH	12	13									
Frequency (MHz)	2467	2474									
Scan Type	Active	Active									

5G band 1

CH	36	38	40	44	46	48				
Frequency (MHz)	5180	5190	5200	5220	5230	5240				
Scan Type	Active	Active	Active	Active	Active	Active				

5G band 2

CH	52	54	56	60	62	64				
Frequency (MHz)	5260	5270	5280	5300	5310	5320				
Scan Type	Passive	Passive	Passive	Passive	Passive	Passive				

5G band 3

CH	100	102	104	108	110	112	116	118	120
Frequency (MHz)	5500	5510	5520	5540	5550	5560	5580	5590	5600
Scan Type	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive
CH	124	126	128	132	134	136	140	142	144
Frequency (MHz)	5620	5630	5640	5660	5670	5680	5700	5710	5720
Scan Type	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive

5G band 4

CH	149	151	153	157	159	161	165
Frequency (MHz)	5745	5755	5765	5785	5795	5805	5825
Scan Type	Active	Active	Active	Active	Active	Active	Active

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before



firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed.

Sincerely yours,

Sincerely yours,

Albert Huang

Albert Huang EMC/Safety Engineer
MICROSOFT CORPORATION
Tel: (86-755)8611 8676
Fax: (86-755)2655 1121
Email: albhuang@microsoft.com