

\$\$ADD NG T261089

TYP01 N

DAT01 260820

CLA01 U

FRQ01 M1090.0000

EXD01 270930

STC01 XT

EMS01 5M60M1D

PWR01 W600.00000

STC02 XT

EMS02 7M30M1D

PWR02 W600.00000

STC03 XT

EMS03 19M30V1D

PWR03 W600.00000

XSC01 CA

XAL01 EDWARDS AFB

XLA01 345526N

XLG01 1175328W

XAD01 02GMONOPOLE

XAP01 V

XAZ01 ND

RSC01 CA

RAL01 EDWARDS AFB

RLA01 345526N

RLG01 1175328W

RAD01 02GMONOPOLE

RAP01 V

RAZ01 ND

BUR01 FCC

BIN01

REM01 *PRR,20K/20K

REM02 *RAD,0080,0043NM,B

REM03 *EQT,C,AN/APX-119RT1861,FX,PD0.5/1.06

REM04 *EQT,C,AN/APX-119RT1861

REM05 *NTS,M014,0600,AGL

REM06 *NTS,M018,FAA ,260820,BLANDO,NG T261089

SUP01 SUPPORTS FLIGHT TESTING OF THE RQ-4D UAS. OPERATIONS SUPPORTED BY
AIMS C

SUP02 L 2428202 AND OCD 2026-WSA-00101. SPECIAL CONDITIONS: 1) MODES 1, 2, 3/A

SUP03 , C, 5 (LEVEL 1 AND 2), S (EHS/ELS), AND ADS-B OUT, 2) TESTING LIMITED T

SUP04 O THE SPECIAL USE AIRSPACE AT EDWARDS AFB, 3) SUPPORTS P.2 SOFTWARE
ON T

SUP05 HE APX-119, PN 4079100-0547, 4) COORDINATE WITH LOCAL ATC TO OBTAIN
MODE

SUP06 2 AND 3/A CODES, 5) MODE 5 LEVEL 1 AND 2 MUST BE DISABLED OUTSIDE OF SU

SUP07 A, 6) STOP BUZZER POC IS NATHAN MILLER (858) 253-7357, OR MARK GRIFFITHS

SUP08 (661) 802-8703.