



170 W Tasman
San Jose CA 95134

September 23, 2009

Reference : FCC ID: LDK102061
EA128460
CRN: 38118
Class II Change

In reference to the FCC guidance on certifications for Part 15.407 devices operating in 5470-5725MHz band, the above listed product was granted approval on 08/30/2007. This grant was issued before the indoor only restrictions were added and not subject to this restriction for the application of this Class II Change

The Cisco product does not operate in the 5600-5650MHz band and the channels cannot be accessed by the user.

Best Regards,

A handwritten signature in blue ink, appearing to read "Jim Nicholson".

Jim Nicholson
EMC Compliance Engineer