

From: Michael Gold

To: Leann Nguyen

Date: March 15, 2021

Subject: Request for Info - File # 0025-EX-CR-2021

Message:

The correct orbital inclination is 64.5 degrees (originally states in whole numbers as 65 degrees in the initial experimental license application). That has remained unchanged throughout the company's operations.

If there are any additional questions, please contact our FCC counsel, David Keir, at dkeir@lermansenter.com or 202-416-6742.

Respectfully submitted,

Susan Gentuso
Bigelow Aerospace, LLC