

To: David Townsend  
E-Mail: dlt@raytheon.com  
From: Jose Trevino  
Date: March 05, 2009

Subject: FCC file number 0078-EX-PL-2009

---

Message:

Mr. David Townsend,

The following information is needed to process the application.

- Please provide a description of its purpose in more detail.
- 1435-1525 MHz with the Aerospace & Flight Test Radio Coordinating Council (AFTRCC), the telephone number is (770) 494-2893.
- 88-108 MHz, 450-456 MHz, 614-806 MHz and 944-960 MHz, coordinate with the Society of Broadcast Engineers.
- The Federal Aviation Administration (FAA) operates the frequency band: 108 -121.9375 MHz. Please prior coordinate the use of the frequency band with the FAA Western Service Area, (WSA) Office at (425) 203-4756.

Please obtain the NGT number(s) from the WSA Office at the completion of the coordination and report it in your response to this correspondence. Please report the parameter below in your coordination with the WSA Office:

- Peak envelope power (PEP);
- Type of antenna;
- Transmit antenna gain;
- Elevation above sea level of the antenna site;
- Height above ground of the focal point of the antenna;
- Antenna polarization;
- The azimuth that the antenna is pointed or appropriate designator to indicate whether the antenna is rotating, non-directional, etc.;
- Pulse repetition rate (PRR) that the equipment is capable of operating on to include PRR stagger sequences if appropriate, whether the PRR is adjustable and what PRR's the equipment can accept, and any other information that would be helpful in understanding the pulse characteristics of the equipment;
- Pulse width;
- Equipment nomenclatures;
- Whether the equipment is capable of blanking transmissions in certain azimuths and any limitations with respect to blanking;
- Radius of operations if appropriate;
- Detailed description of the proposed operation to include any technical parameters that will be altered during operations.

Phone numbers to the FAA Regional Frequency Management Offices may be obtained at:  
[www.faa.gov/ats/aaf/locations/fmos.htm](http://www.faa.gov/ats/aaf/locations/fmos.htm)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of March 05, 2009 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://gulfoss2.fcc.gov/prod/oet/cf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 8109