

To: Jason Euting
E-Mail: jeuting@textron.com
From: Leann Nguyen
Date: June 24, 2021

Subject: Request for Info - File # 0636-EX-ST-2021

Message:

FCC is unable to process the application prior to starting date and many errors on the application, please review carefully before re-submitting the application.

- Provide city/state, address on each antenna on the application
- Provide ERP on each frequency band,
- The applied frequency bands has wrong emission designators. The bandwidth of emission designators are exceeded the applied frequency bands such as antenna 9, 10, 12...
- Provide stop buzzer information including name and telephone number.
- Provide FAA NG T numbers for the following frequency bands: 330-335 MHz, 1350-1390 MHz and 1090 MHz.
- Please verify start/end date. The cover letter and details and AFTRCC coordination are showing the operation date 07/07/2021-07/30/2021, but the application form is showing 06/21/2021-12/21/2021.
- Please verify ERP on AFTRCC frequency band. On the AFTRCC coordination it shows ERP is 5W, but on the application it shows 10W.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of June 24, 2021 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 62933