

The Boeing Company
P.O. Box 3707
Seattle, WA 98124-2207

April 11, 1996
G-8930-GCB-115

Federal Communications Commission
Experimental Radio Services
P.O. Box 358320
Pittsburgh, PA 15251-5315

BOEING


Subject: Modification of FCC License KF2XJK

The enclosed FCC Form 442 is submitted to modify FCC license KF2XJK. The FAA requires the Terrestrial Flight Telephone System (TFTS) be tested in flight as part of the aircraft certification. Presently Boeing only has a verbal from the FAA, when the formal requirement is received, a copy will be forwarded.

Boeing requires only one site for the flight test portion. We would prefer either Seattle, WA or Glasgow, MT if possible.

Boeing is willing to work with any present user to preclude the possibility of harmful interference being received by the present users.

Should additional information be required, please contact Gerry Broerman at (206) 657-6420.



J. H. Rogneby
Frequency Manager
G-8930, 3U-AJ
(206) 657-6095

Enclosures:

FCC Form 442
FCC Check 0133757