

To: Dakota Neilson
E-Mail: Flightops@versatol.com
From: Leann Nguyen
Date: March 09, 2021

Subject: Request for Info - File # 0224-EX-ST-2021

Message:

We are unable to process your application because the information is inaccurate. Please provide the following information

- The company must update the location on the application. The applicant is responsible for any updates or changes the information on the application.
- Provide the explanation for "X" letter in emission designator. What is the modulation signal that the company would like to use?

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of March 09, 2021 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 60534