

We are a Porsche Authorized Service Center. GPS signal (6 satellites) is required to conduct various repairs of Porsche vehicles. Porsche corporate recommends that we acquire and operate a GPS repeater to be able to conduct these repairs inside of our service shop. Currently, the signal does not allow for this work to be conducted indoors and technicians are required to move the vehicle outside to receive adequate signal.