



1700 International Parkway, Suite 200, Richardson, TX 75081, USA

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

**Subject: Request to change in identification per section 2.933 of FCC rules**

Date: 2021-09-03

Reference: **FCC ID: 2AWAS-910-00084**

To The Commission:

This Change of Identification request applies for a new **FCC ID: 2AWAS-910-00084** as established in 47CFR 2.933(b) for a currently approved device. This application by **Mavenir Systems, Inc.** will establish a new FCC ID under our own **2AWAS** grantee code for purpose of marketing. The original grant issued to Microelectronics Technology Inc. under **FCC ID: MAD-G08RRH-46-06B** will remain in effect.

Per 2.933(b)

1. The original identification is **FCC ID: MAD-G08RRH-46-06B**
2. The original grant date is **07/01/2020**
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

**Cover Letter**

**External Photos**

**FCC ID label format and location**

Sincerely yours,

A handwritten signature in blue ink, appearing to read 'Jadran Lokas', with a horizontal line underneath.

-----  
Jadran Lokas/ Senior Director Systems, Partners & Verification – Radio  
Mavenir Systems, Inc.  
TEL: +1 (613) 864 8037  
E-mail: [Jadran.lokas@mavenir.com](mailto:Jadran.lokas@mavenir.com)  
Date: 09/02/2021