

FCC ID: AZ489FT7144

Date: November 1, 2021

Authorization & Evaluation Division Federal Communications Commission Laboratory 7435 Oakland Mills Road Columbia, MD 21046

Subject: Extended Frequencies Justification for Certification of Transmitter with FCC ID: AZ4489FT7144

Dear Sir/Madam:

This transmitter is designed to operate in the following frequency ranges:

| Band/Mode | Frequency ranges | FCC rule parts | | |
|--------------|------------------|----------------|--|--|
| VHF | 136 - 174 MHz | 22, 74, 90 | | |
| VHF | 156.0 – 162 MHz | 80 | | |
| Bluetooth | 2402 – 2480 MHz | 15C | | |
| Bluetooth LE | 2402 – 2480 MHz | 15C | | |
| Wi-Fi/WLAN | 2412 – 2462 MHz | 15C | | |
| Wi-Fi/ WLAN | 5170 – 5835 MHz | 15E | | |

To aid equipment authorization in other countries which accept the United States FCC Grant for Certification, Motorola Solutions is requesting that the FCC lists the above applicable frequencies range under FCC Rule Parts 22, 74, 80, and 90 on the FCC Grant.

For the FCC's Rule Parts 22, 74, 80 and 90 applications, this radio is used in systems by Federal and Public Safety agencies including Police, Fire, and Emergency Medical Services, etc. as indicated in the table below. Equipment programming is the responsibility of Authorized Service Personnel.

Also, the radio complies with 47 CFR Part 90.203(e) and 80.203(b), in that the operator cannot directly program the transmit frequencies using the normally accessible external controls.

Per the FCC's KDB634817 guidance, as an alternative to listing the exact frequencies, we acknowledge that it's a violation of the FCC Rules if this device operates on unauthorized frequencies.

| Frequency Range (MHz) | Part 22 | Part 74 | Part 80 | Part 90 | Federal | Other Regions |
|--------------------------|---------|---------|---------|------------|---------|------------------|
| 136-150.8* | | | | | Х | Х |
| 150.8-152.855 | | | | Х | | |
| 152.855-154 | | Х | | Х | | |
| 154-156.2475 | | | х | Х | | |
| 156.2475-157.1875 | | | х | | | |
| 157.1875-157.45 | | | х | Х | | |
| 157.45-161.575 | Χ | Χ | х | Х | | |
| 161.575-161.625 | | | Х | | | |
| 161.625-161-775 | | Х | | | | |
| 161.775-161.9625 | | | х | Х | | |
| 161.9625-162.025 | | | х | | | |
| 162.025-162.0375* | | | | | Х | Х |
| 162.0375-173.4 | | Х | | Х | | |
| 173.4-174* | | | | | | Х |

*Canada

Please contact me if you required any additional information.

Sincerely,

Arine Lee

FCC/IC Certification Manager

E-mail: arinelee@motorolasolutions.com