

**MOTOROLA SOLUTIONS****Exhibit 7B MPE Test Report Photographs****Motorola Solutions Inc.****EME Test Laboratory**

Motorola Solutions Malaysia Sdn Bhd  
Plot 2A, Medan Bayan Lepas,  
Mukim 12 SWD 11900 Bayan Lepas Penang, Malaysia.



**Tey Pei Loo**  
**Deputy Technical Manager (Approved Signatory)**  
**Approval Date:**

## Document Revision History

| Date       | Revision | Comments        |
|------------|----------|-----------------|
| 11/06/2020 | A        | Initial release |

## 1.0 Antenna Photograph(s)



**VHF Antenna kit numbers, from left to right  
HAD4006A, HAD4007A, HAD4008A, HAD4009A**



**VHF Antenna kit numbers, from left to right  
RAD4226A, RAD4227A, RAD4224A, RAD4223A**



**VHF Antenna kit numbers**  
HAD4022A (6 pcs)

Note: Antenna length trimmed to frequency.




**VHF Antenna kit numbers**  
RAD4225A


## 2.0 Test Measurement Setup Photos




Test measurement setup for Bystander, trunk mount antenna behind vehicle



Test measurement setup for Bystander 45 degree (diagonal) trunk mount antenna



Test measurement setup for Bystander 90 degree (side) trunk mount antenna




Test measurement setup for Bystander roof mount antenna



Test measurement setup for Passenger Back




Test measurement setup for Passenger Front



Test positions for Passenger Back and Front

### 3.0 Magnetic mount base for antenna installation photos



**Magnetic mount base (top and side view)**