

April 19, 2013

Jim Nicholson EMC Compliance Engineer Cisco Systems, Inc. 4125 Highlander Parkway Richfield, OH 44286

Re: FCC ID: LDK102086

Applicant: Cisco Systems Inc

Correspondence Reference Number: 43722
Form 731 Confirmation Number: EA730561
Date of Original E-mail: 04/19/2013

1. Please also address the use of Channel 142 (5710 MHz). Operation of 40 MHz mode would exceed the UNII 2e band (5470-5725 MHz)

This product only supports channels in the 100 (5500 MHz) to 140 (5700 MHz) range. Channel 142 is not supported.

2. Please present test data in the EMC report to show compliance with 15.407(g) rule over the normal operation temperature range and voltage fluctuation.

See updated 5470-5725 MHz Test Report.

3. Please remove the reference of the non-existent section especially now the EMC report is to be revised.

See updated 5470-5725 MHz Test Report.

Best Regards,

Jim Nicholson

EMC Compliance Engineer

Phone: (330) 523-2094 Fax: (330) 523-2002 E-Mail: jimnicho@cisco.com