



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

August 24, 2004

RE: Delta Networks, Inc

FCC ID: PD5LMWA800RA

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The Block Diagram does not meet the requirements of 2.1033(b)(5). In fact, when I compare it to the Schematics, I cannot correlate the two documents. Kindly review.
- 2.) The RF Pout shown on page 41 of the Test Report does not appear to be measured values. These values shown are very good – too good. I do not believe that all channels showed exactly the same Pout across all three channels in both CCK and OFDM modes. FCC regulations require the use of measured power values and not rated power. This measured power should be shown in the Test Report and on Form 731. Please provide revised Test Report and Form 731.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.