




Physical Test arrangement Photograph:



Title: 10dBi Band Edge Test Setup



Physical Test arrangement Photograph:

Title: Colocation Test Configuration



Physical Test arrangement Photograph:



Comments on the above Photograph:

Bilog antenna in background used to measure 30Mhz to 1Ghz range.



Physical Test arrangement Photograph:



Comments on the above Photograph:

Power supply plugged into LISN mounted under Turntable.