

Test Setup Photograph	
Equipment Tested (Company, Model) United Service Equipment Co., Unitron	FCC ID: P7M-Unitron

Photograph of Radiated Emissions Test Setup



The dates on the photos are incorrect. They should be 1/22/02 for the Radiated and 1/23/02 for the Conducted emissions test.

Photograph of Conducted Emissions Test Setup



